

BARTINGTON

MAG-03MC-CU & MAG-03MS-CU

CALIBRATION UNIT

OPERATION MANUAL

Distributed by:

GMW Associates

955 Industrial Road, San Carlos, CA 94070 USA

Tel: (650) 802-8292 Fax: (650) 802-8298

Email: sales@gmw.com

website: <http://www.gmw.com>

Manufactured by:

Bartington Instruments Ltd.

10 Thorney Leys Business Park

Witney, Oxford OX8 7GE

England

Tel: 011 44 1993 706565 Fax: 011 44 1993 774813

Email: sales@bartington.com

website: <http://www.bartington.com>

Issue 3

OM1300

**OPERATION MANUAL
Mag-03MC-CU & Mag-03MS-CU
CALIBRATION UNITS**

Bartington Instruments Ltd
10 Thorney Leys Business Park
Witney
Oxford
OX28 4GG
England
Telephone +44 1993 706565
Facsimile +44 1993 774813
E-mail sales@bartington.com
Internet <http://www.bartington.com/>

In the interest of product improvement, Bartington Instruments Ltd. reserve the right to change any part of the design of this product without prior notice.

This product is not qualified for use in explosive atmospheres or life support systems. Consult Bartington Instruments for advice.

The copyright of this document is the property of Bartington Instruments Ltd. The document is supplied on the condition that it is to be treated commercially confidential and it may not therefore be disclosed to any third party without the written authorisation of the Directors of Bartington Instruments.



**(89/336/EEC)
EMC DIRECTIVE**

CONTENTS

1. Mag-03MC-CU Calibration Unit
 - 1.1 General Description
 - 1.2 Construction
 - 1.3 Checking the battery
 - 1.4 Using the calibration unit
 - 1.4.1 *Mag-03MC-CU*
 - 1.4.2 *Mag-03MS-CU*
 - 1.4.3 *Mag-03MC-CU* with IE adaptor
 - 1.5 Changing the battery
 - 1.6 Technical specifications
 - 1.7 Fault diagnosis

Figures

- | | |
|-----------|---|
| Figure 1 | <i>Mag-03MC-CU</i> Outline drawing |
| Figure 2 | <i>Mag-03MC-CU</i> Photograph |
| Figure 3 | <i>Mag-03MC-CU</i> X & Y measurement position |
| Figure 4 | <i>Mag-03MC-CU</i> Z measurement position |
| Figure 5 | <i>Mag-03MS-CU</i> Outline drawing |
| Figure 6 | <i>Mag-03MS-CU</i> Photograph |
| Figure 7 | <i>Mag-03MS-CU</i> Z measurement position |
| Figure 8 | <i>Mag-03MS-CU</i> X & Y measurement position |
| Figure 9 | <i>Mag-03MC-CU</i> with IE adaptor outline drawing |
| Figure 10 | <i>Mag-03MC-CU</i> with IE sensor adaptor |
| Figure 11 | <i>Mag-03MC-CU</i> with IE measurement position |
| Figure 12 | Output response of <i>Mag-03</i> for 50 μ T p-p (17.7 μ T rms) Sinewave Test Signal |

1 *Mag-03MC-CU* CALIBRATION UNIT

1.1 General description - Figures 1 & 2 and 5 & 6

The *Mag-03MC-CU* and *Mag-03MS-CU* calibration units are battery powered units which produce a sinusoidal alternating magnetic field of defined frequency and magnitude.

The unit provides a reference magnetic field for testing the calibration of the *Mag-03MC* cylindrical, *Mag-03MS-CU* square, fluxgate sensors in the field or in the laboratory.

1.2 Construction

The calibration unit comprises a set of coils wound on a cylindrical former which contains the drive electronics and battery. The coils are of the Helmholtz type and produce a very uniform magnetic field along the axis of the cylindrical enclosure. The cylinder possesses two holes into which the magnetometer under test is placed. One hole is along the axis of the enclosure and is used to test the Z axis. The other is through the diameter and is used to test the X and Y axes.

1.3 Checking the battery

The unit should be switched on and the battery level indicator observed. A green light indicates that the battery is satisfactory. A yellow light indicates that the battery should be changed immediately but that the unit is still working. A red light indicates that the battery should be changed immediately as it is below the level at which the calibration unit will operate.

1.4 Using the calibration unit

A suitable test site, well away if possible from known sources of magnetic noise, should be chosen. The test must be carried out in an area at least 0.5 metres away from any large ferrous objects or electrically conductive surfaces. For example, measurements should not be attempted with the calibration unit placed on a metal table top. Consult the table given in Figure 12 for output response voltages.

1.4.1 *Mag-03MC-CU* - Figures 3 & 4

Place the *Mag-03MC* sensor in the axial hole of the calibration unit and position the Z sensor arrow marked on the *Mag-03MC* body midway between the two white coils. The position can be seen by looking through the transverse hole. Measure the Z axis sensor output using a true rms digital voltmeter, oscilloscope or spectrum analyser and adjust the position of the sensor in the calibration unit to obtain a maximum reading. The value should be 50 μ T peak-to-peak or 17.7 μ T rms $\pm 1.5\%$ taking the tolerance of the sensor and calibration unit into account.

Place the magnetometer in the transverse hole in the calibration unit and select the X axis for measurement. Align the arrow indicating the X axis with the centre of the axial hole and pointing along the axis of the coils. Rotate the *Mag-03MC* slightly to obtain a maximum output voltage. Repeat this for the Y axis.

1.4.2 *Mag-03MS-CU* - Figures 3 & 4

Place the *Mag-03MS* sensor all the way into the axial hole of the calibration unit. This will position the Z sensor arrow marked on the *Mag-03MS* body, midway between the two white coils. The position can be seen by looking through the transverse hole. Measure the Z axis sensor output using a true rms digital voltmeter, oscilloscope or spectrum analyser and adjust the position of the sensor in the calibration unit to obtain a maximum reading. The value should be 50 μ T peak-to-peak or 17.7 μ T rms $\pm 1.5\%$ taking the tolerance of the sensor and calibration unit into account.

Place the magnetometer in the transverse hole in the calibration unit and select the X axis for measurement. Align the arrow indicating the X axis with the centre of the axial hole and pointing along the axis of the coils. Repeat this for the Y axis.

1.4.3 *Mag-03MC-CU* with IE adaptor - Figures 9, 10 & 11

Locate the *Mag-03IE* sensor in the IE adaptor and slide into the axial hole of the *Mag-03MC-CU*. Slide back and forth to achieve the highest reading. Repeat for all axes

1.5 Changing the battery

This should be done on a table. Remove the three M3 screws which secure the control panel. Carefully remove the panel taking care not to damage the twisted wire connecting the coils to the circuit board. Remove the old battery and replace with a new one. Switch on and check that the new battery has been installed correctly and that the unit is working. Carefully replace the cover and the retaining screws.

1.6 Technical specifications

Mechanical

Dimensions : MC - 125 mm length, 100 mm diameter
MS - 116 mm length, 100mm diameter

Weight : MC - 1.05 kg
MS - 0.98 kg

Environmental : IP 61 Not suitable for use in wet conditions

Electrical

Battery type : PP3 9 V alkaline or lithium dioxide fitted internally

Battery life : Approximately 40 hours continuous use

Battery indicator : Tri-colour LED
Green - charged
Yellow - low charge
Red - change battery

On/off switch : Recessed in control panel

Performance

Frequency : 190 Hz $\pm 2\%$

Sinewave purity : approx. 5% distortion

Sinewave magnitude : 50 μT p-p $\pm 1\%$

1.7 Fault diagnosis

If the calibration unit fails to produce the expected response then the following should be checked:

- (1) that the power supply is switched on
- (2) that the magnetometer is not subjected to a large magnetic field and is overloaded

- (3) that the connectors are all secure

Faulty cables can be tested using an electrical resistance meter. If the fault cannot be remedied or the sensor is out of calibration it should be returned to Bartington Instruments or your local representative, preferably with an accompanying brief description of the problem.




FIGURE 1



FIGURE 2



FIGURE 3



FIGURE 4




FIGURE 5



FIGURE 6



FIGURE 7



FIGURE 8




FIGURE 9




FIGURE 10




FIGURE 11

OUTPUT RESPONSE OF *Mag-03* FOR 50 μ T P-P (17.7 μ T RMS) SINEWAVE TEST SIGNAL

CALIBRATION RANGE / 10V	V _{OUT} P-P	V _{OUT} RMS
70 μ T	7.14	2.53
100 μ T	5	1.77
250 μ T	2	0.708
1000 μ T	0.5	0.177

FIGURE 12