**Technical Note** 

## <u>GMW</u>

## TNG3DTM002a - Grounding of Group3 Digital Teslameters

**Caution:** The following procedure requires working with and around high voltages. Please exercise extreme caution when doing so, or refer to a qualified person to do the work for you.

For proper grounding and transient protection of the Group3 DTM, please refer the drawing number 11901610 and follow the steps outlined below.

Items required:

- 1. DTM & Probe with shielded cable
- 2. Ferrite Kit, P/N 11000036 (ferrite for probe cable and DTM power input cable)
- 3. DTM Ground Wire; 1.5mm(16AWG) minimum, length as required
- 4. Power Supply Ground Wire; 1.5mm(16AWG) minimum, length as required
- 5. Power Supply, P/N 21000010
- 6. AC Power Cord
- 7. Optional: Fiber optic cables for RS-232 interface

## DTM and Power Supply:

- 1. Remove the chassis screw on the DTM nearest the power input socket.
- 2. Remove the paint from the area around the screw that you have just removed.
- 3. Attach the DTM ground wire to the DTM using the chassis screw. Connect the other end to the rack or system chassis ground point near the DTM
- 4. Install the power supply as close as possible to the DTM.
- 5. Trim the DTM power input cable as short as possible and connect it to the power supply. Connect the other end to the DTM.
- 6. Attach one end of the power supply ground wire to the AC input ground terminal, and the other end to the SAME rack or system chassis ground point as the DTM.
- 7. Attach the AC power cord to the power supply.
- 8. Connect the fiber optic cables if required

## Probe:

- 1. Install the clip-on ferrite supplied in the ferrite kit to the probe cable, as close as possible to the probe personality plug as shown.
- 2. Connect the probe to the DTM.

If you have any questions, please feel free to contact GMW Technical Support at: Tel: (650) 802-8292 Ext. 18 Fax: (650) 802-8298 E-mail: greg@gmw.com

