


# FIBRE OPTIC CONNECTOR CLEANING INSTRUCTIONS

Drawing No 72791-HB issue 2 07.05.08 CR2555




## Connectors

The usual convention for connector colour coding is:-

FC-APC connectors are generally GREEN (some cross site cables also use BLUE)

FC-PC connectors are generally BLUE or BLACK



## CLEANING KIT CONSUMABLES

DESCRIPTION	PPM Part Number
Cleaning Cassette	54030
Cleaning Cassette replacement tape	54031
Cleaning sticks	54032
Lint free wipes (per pack)	97112
Dust Caps (green) for FC/APC receptacles	52592
Dust Caps (black) for ST receptacles	52588