





Current Control Input	
Hirose RM15-TRD-10S	
Pin No	Function
1	X+ SIGNAL
2	Y+ SIGNAL
3	Z+ SIGNAL
4	POWER GROUND
5	N.C.
6	N.C.
7	N.C.
8	X- SIGNAL
9	Y- SIGNAL
10	Z- SIGNAL

Current Monitor Output	
Hirose RM15-TRD-10P	
Pin No	Function
1	X+ SIGNAL
2	Y+ SIGNAL
3	Z+ SIGNAL
4	POWER GROUND
5	N.C.
6	N.C.
7	N.C.
8	X- SIGNAL
9	Y- SIGNAL
10	Z- SIGNAL

Output to Helmholtz Coil	
Neutrik NLT8MP	
Pin No	Function
1+	X+
1-	X-
2+	Y+
2-	Y-
3+	Z+
3-	Z-
4+	GROUND
4-	N.C.




Bartington®
Instruments

COPYRIGHT: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS CONFIDENTIAL AND MUST NOT BE REPRODUCED, COPIED OR USED FOR ANY PURPOSE WHATSOEVER WITHOUT THE PRIOR PERMISSION OF BARTINGTON INSTRUMENTS LTD.

DIMENSIONS ARE IN MILLIMETERS

THIRD ANGLE PROJECTION



TOLERANCES FOR MACHINING: (UNLESS OTHERWISE SPECIFIED)

LINEAR:	ANGULAR:
XX ±0.3mm	XX ±0.5°
XX.X ±0.1mm	XX.X ±0.1°
XX.XX ±0.05mm	XX.XX ±0.05°

TITLE
**PA1 Power Amplifier
Outline Drawing**

TECHNICAL INFORMATION No.	T12613
OPERATION MANUAL No.	OM3225
DATASHEET No.	DS2613

USED ON		PROJECT No
DRAWN	<i>Munir Khaled</i>	17/05/2013
MODIFIED	<i>Robert Arnold</i>	12/09/2016
MECH' CHECK	<i>Luke Fry</i>	18/02/2016
ELEC' CHECK	<i>Jeff Dando</i>	12/09/2016
DRAWING No	DR3047	ISSUE
		4
		SEE DCN NUMBER FOR DESIGN CHANGE HISTORY